

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 5
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 06/17/2009
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S01AA1003MH	Test ID: S1032-026045	Notifications (Residents, Fire, 311) : Yes



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 5
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 06/17/2009
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S01AA1003MH	Test ID: S1032-026045	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Service Lateral; Smoke:

Light; Status: Private Property


Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 5
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 06/17/2009
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S01AA1003MH	Test ID: S1032-026045	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Service Lateral; Smoke:

Medium; Status: Private Property

Defect




Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 5
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 06/17/2009
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S01AA1003MH	Test ID: S1032-026045	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Main Sewer; Smoke:

Light; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property

Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 5 of 5
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 06/17/2009
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S01AA1003MH	Test ID: S1032-026045	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Downspout; Smoke: Medium; Status: Private Property

Landscape



